

INSTRUCTIONS

UTRAP

072009v1



Ultimate Trap

PARTS LIST

One Tunnel Gourd Entrance

One Tube Guide

Two Metal Guides

One Rounded Porch Floor


One Squared Porch Floor

One Entrapment Arm

Four White Snaps

Two Black Plastic Stars

One Metal Trap Door



**IF ANY ITEM IS
DISCOVERED MISSING,
CALL 1-800-764-8688
DO NOT RETURN TO STORE.**

S&K Manufacturing, Inc.
1001 Liberty Industrial Drive
O'Fallon, Mo 63366
www.skmg.com
1-800-764-8688





Insert the Tube Guide through the small hole above the tunnel entrance. The Tube Guide will be very snug.



Insert the Rounded Porch Floor at the front of the Tunnel Entrance.


Insert the Squared Porch Floor at the back of the Tunnel Entrance.




Push Black Plastic Star over the Tube Guide at the front of the Tunnel and at the rear of the Tunnel. The Black Plastic Stars will be very snug.



Attach the two Metal Guides - one on each side of the tunnel as shown. The Metal Guides attach with two White Snaps on each Metal Guide being inserted to the corresponding holes on the Tunnel Gourd Entrance, as shown.



Insert the Entrapment Arm through the Tube Guide from the back of the Tunnel.



Insert the Metal Trap Door into the two Metal Guides. The Entrapment Arm at the front of the Tunnel will hold the Metal Trap Door in place just above the Tunnel Entrance. Attach the tunnel to the your S&K Gourd and set the trap.